

Basic Vehicle Condition Guide

Report ID: 18,591,110


Version:

Created: 07 Oct 2018

Make: Model: Holden Colorado **Body Style:** Utility Year: Registration: FAW513 Reg Expiry: 27 Jul 2019 2009 WoF Expiry: **Odometer:** 11 Oct 2018 **Good No:** 18591110 145,382 Kms VIN: MMMTFR85H8H57843 **Next Service: Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Aftermarket parts fitted on top of the roof Front bumper misaligned

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

AC not getting cold

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

07 Oct 2018 Inspected by: Xinghui Lin Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	
Operation	~		
Noise	V		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3	.5	mm
Right front	3.5		mm
Left rear	2		mm
Right rear	2		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		<u> </u>
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	·		
Remote locking	·		
Sat. Nav. (basic test only)			~
Land (Subset test of hy)	I	Ì	ļ -
Reversing camera			V

Signature: