

I have read and understood this condition guide.

Report ID: 18,591,451 Version: 1 Created: 23 Oct 2018

Signature:

Make:	Holden	Model:	Adventra	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	LRP189	Reg Expiry:	10 May 2019	Engine	11		
WoF Expiry:	17 Oct 2019	Odometer:	179,410 Kms	Good No:	18591451	Oil level	~		
VIN:	6G1ZM84795L541261	Next Service:	189000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	11		L
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			C.W.			Performance	~		
Key:		-0	SW SPTW	-M-	s	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc w			715	HILW	Operation	~		
PT = paint def		F		$\left[\left(\right) \right]$		Noise	~		
C = crack					w	Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sscw 91				ED sw	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	w w		W			Performance	~		
Pedulac	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		<u> </u>
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Roof lining loose at rear Drivers door trim loose						Left front	Left front 5.0 r		
						Right front	5.	-	mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear			mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		1
Carpets	Average					Indicators	~		
Panels	rear door o	cards damaged				Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·					Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1		
Inspected by: Greg Morgan Date: 10 Oct 2018									

Name: