

Report ID: 18,591,737


Version:

Created: 19 Oct 2018

| Make:       | Mini             | Model:        | Cooper S    | Body Style:     | Hatchback     |
|-------------|------------------|---------------|-------------|-----------------|---------------|
| Year:       | 2008             | Registration: | ESU497      | Reg Expiry:     | 01 Oct 2019   |
| WoF Expiry: | 22 Oct 2019      | Odometer:     | 135,930 Kms | Good No:        | 18591737      |
| VIN:        | WMWMF72040TV0402 | Next Service: | n/a         | Service History | <b>y:</b> Yes |

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

| Interior Comments |      |  |  |  |  |
|-------------------|------|--|--|--|--|
| Seats             | Good |  |  |  |  |
| Carpets           | Good |  |  |  |  |
| Panels            | Good |  |  |  |  |
| Dashboard         | Good |  |  |  |  |

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 05 Oct 2018 Inspected by: lan Dunn

|   | Pass                                  | Fail    | N/A      |  |  |  |  |  |
|---|---------------------------------------|---------|----------|--|--|--|--|--|
| Engine  |                                       |         |          |  |  |  |  |  |
| Oil level                                     | ~                                     |         |          |  |  |  |  |  |
| Smoke & fumes                                 | V<br>V                                |         |          |  |  |  |  |  |
| Performance                                   | ~                                     |         |          |  |  |  |  |  |
| Noise   | ~                                     |         |          |  |  |  |  |  |
| Cooling System                                |                                       |         |          |  |  |  |  |  |
| Coolant condition                             | ~                                     |         |          |  |  |  |  |  |
| Performance                                   | \( \sigma \)                          |         |          |  |  |  |  |  |
| Radiator / Hoses (visual)                     | ~                                     |         |          |  |  |  |  |  |
| Transmission                                  |                                       |         |          |  |  |  |  |  |
| Operation                                     | V V                                   |         |          |  |  |  |  |  |
| Noise   | ~                                     |         |          |  |  |  |  |  |
| Clutch  |                                       |         | ~        |  |  |  |  |  |
| CV joints                                     | ~                                     |         |          |  |  |  |  |  |
| Wheel bearings                                | ~                                     |         |          |  |  |  |  |  |
| Brakes  |                                       | ı       |          |  |  |  |  |  |
| Performance                                   | ~                                     |         |          |  |  |  |  |  |
| Hand Brake                                    | ~                                     |         |          |  |  |  |  |  |
| Tyres (lowest observed tread                  | depth                                 | of tyre | es)      |  |  |  |  |  |
| Left front                                    | 5                                     | .3      | mm       |  |  |  |  |  |
| Right front                                   | 5                                     | .2      | mm       |  |  |  |  |  |
| Left rear                                     | 7                                     | .2      | mm       |  |  |  |  |  |
| Right rear                                    | 6                                     | .3      | mm       |  |  |  |  |  |
| Spare   |                                       | No      |          |  |  |  |  |  |
| Suspension                                    |                                       | ı       |          |  |  |  |  |  |
| Suspension performance                        | ~                                     |         |          |  |  |  |  |  |
| Steering performance                          | ~                                     |         |          |  |  |  |  |  |
| Shock absorbers                               | ~                                     |         |          |  |  |  |  |  |
| Air Conditioning / Heater                     |                                       | I       |          |  |  |  |  |  |
| Operation                                     | •                                     |         |          |  |  |  |  |  |
| Electrical / Accessories                      |                                       |         |          |  |  |  |  |  |
| Head lights                                   | <i>\</i>                              |         |          |  |  |  |  |  |
| Tail lights                                   | •                                     |         |          |  |  |  |  |  |
| Indicators                                    | •                                     |         |          |  |  |  |  |  |
| Dashboard warning lights                      | •                                     |         |          |  |  |  |  |  |
| Wipers (front & rear) Window winder FL        | > > > > > > > > > > > > > > > > > > > |         |          |  |  |  |  |  |
|   | <i>V</i>                              |         |          |  |  |  |  |  |
| Window winder FR                              |                                       |         |          |  |  |  |  |  |
| Window winder RL                              | <i>V</i>                              |         |          |  |  |  |  |  |
| Window winder RR Rear view mirrors            |                                       |         |          |  |  |  |  |  |
|   | \( \times \)                          |         |          |  |  |  |  |  |
| Radio (basic test only)  CD (basic test only) | <i>v</i>                              |         |          |  |  |  |  |  |
| Number of keys                                |                                       |         | <u> </u> |  |  |  |  |  |
| Central locking                               | 2                                     |         |          |  |  |  |  |  |
| Remote locking                                | •                                     |         | _        |  |  |  |  |  |
| Sat. Nav. (basic test only)                   |                                       |         | .,       |  |  |  |  |  |
| Reversing camera                              |                                       |         | ./       |  |  |  |  |  |
| eversing cumera                               |                                       |         |          |  |  |  |  |  |

I have read and understood this condition guide.

Name: .....

Signature: .....