

## **Basic Vehicle Condition Guide**

Report ID: 18,591,927

Pass

Version:

Created: 01 Nov 2018


Fail

N/A

Make: Model: Subaru **Body Style:** Wagon Forester Year: Registration: Reg Expiry: 1997 CGT148 28 Apr 2019 WoF Expiry: **Odometer:** 23 Feb 2019 **Good No:** 18591927 212,456 Kms VIN: 7A8GF170704004802 **Next Service: Service History:** 221,530kms No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Fog lights or blanks missing. L/H head light chipped.

R/H wing mirror casing cracked.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Oil leaks.

<u>Interior Comments</u>			
Seats	average, dirty .		
Carpets	Average		
Panels	cargo blind missing. dirty head lining.		
Dashboard	Average		

No

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** 

**Daryll Timms** 

Kms:

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \times \)		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	l.0	mm
Right front	3	3.0	mm
Left rear	$\epsilon$	5.0	mm
Right rear	6.0 mm		
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		_	
Head lights	~		
Tail lights	~		
Indicators	<b>V</b>		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	<b>v</b>		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	•	
Central locking	~		
Domoto locking		1	
Remote locking	~		

I have read and	understood this	condition guide.

05 Oct 2018

1

Reversing camera