

Report ID: 18,592,375

Version:

Created: 12 Oct 2018 Pass

Fail

N/A


mm

 $\mathsf{mm}$  $\mathsf{mm}$ 

 $\mathsf{m}\mathsf{m}$ 

3

Make:	Toyota	Model:	Hilux	Body Style:	Utility
Year:	2015	Registration:	JDQ795	Reg Expiry:	28 Mar 2019
WoF Expiry:	29 Jun 2019	Odometer:	114,188 Kms	Good No:	18592375
VIN:	MR0FZ29G901748222	Next Service:	115,000kms	Service Histor	<b>y:</b> Yes



Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** 

I have read and understood this condition guide.

Ca Thach

Inspected by:

No

Central locking Remote locking Sat. Nav. (basic test only) 1 Kms: Reversing camera Date: 12 Oct 2018 Name: ..... Signature: .....

Year:	2015	Registration:	JDQ795	Reg Expiry:	28 Mar 2019		Engine				
WoF Expiry:	29 Jun 2019	Odometer:	114,188 Kms	Good No:	18592375		Oil level	~			
VIN:	MR0FZ29G901748222	Next Service:	115,000kms	Service Histor	r <b>y:</b> Yes		Smoke & fumes	~			
1 -							Performance	~			
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	t been dismantled o	r	Noise	~			
diagnostic tes	sting undertaken. The vical inspection prior to	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommend		Cooling System	•			
a ruii mechan	ical inspection prior to	purchase and the	nis can be arranged id	or an additional	cnarge.		Coolant condition	<b>'</b>			
			SS		S		Performance	<b>'</b>			
<b>Key:</b> S = scratch		=(O)		2(0)=			Radiator / Hoses (visual)	~			
5 = scratcri D = dent	NE				- APP	_	Transmission				
R = rust S C SC							Operation	<b>'</b>			
PT = paint defect						_	Noise	<b>'</b>			
C = crack						┙	Clutch	~			
P = pin dent	sc di8				ZHIIL	23	CV joints	~			
* = decals	(IIE			7			Wheel bearings	~			
SC = stone chi <sub>l</sub> W = significant	/	$\mathbf{Y}(Q)$		200	~		Brakes				
w = signilicani	S		SS				Performance	<b>'</b>			
Rody Incr	nection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagran	1	Hand Brake	~			
Body Inspection Comments  Both running boards dented							Tyres (lowest observed tread depth of tyres				
bour fulllling boards deficed							Left front 6.			m	
							Right front	6.5	5	m	
							Left rear	9		m	
Condition	ns During Body Insp	oection:	Wet				Right rear	9		m	
Conditions burning body inspection.					4	Spare		Yes	_		
<u>Under Ca</u>	rriage & Under Bor	net Inspection	on Comments				Suspension			_	
							Suspension performance	<b>'</b>			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
						_	Operation	<b>'</b>			
Interior C	<u>omments</u>						Electrical / Accessories				
Seats	Good						Head lights	<b>'</b>			
	Good						Tail lights	~			
Carpets	dood						Indicators	~			
Panels	Good						Dashboard warning lights	~			
	, Good						Wipers (front & rear)	~			
Dashboa	rd						Window winder FL	~			
	<u> </u>					_	Window winder FR	~			
General Comments					Window winder RL	~		H			
							Window winder RR	~			
							Rear view mirrors	·			
							Radio (basic test only)	~		H	
							CD (basic test only)	~			
							Number of keys	3			
						_					