

Report ID: 18,592,745 Version: 1 10 Oct 2018 Created:

Make:	Mercedes-Benz	Model:	ML350	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	JUP688	Reg Expiry:	19 Nov 2018	Engine			
WoF Expiry:	17 May 2019	Odometer:	875,606 Kms	Good No:	18592745	Oil level	~		
VIN:	WDC1641862A061188	Next Service:	17/11/18	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	W	-0		-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent $R = rust$ W						Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74 <u>11</u> 4	CV joints	~		
* = decals	sscw 916			-July		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Bodylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front	7.		mm
						Left rear	2		mm
Conditions During Body Inspection: Dry						Right rear	2		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor powe	er steer leak					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
<u> </u>	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	•				1	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			- ' y			Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Greg Morgan Date: 09 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: