

Report ID: 18,593,329 Version: 1 Created: 08 Oct 2018

Make:	Volkswagen	Model:	Passat	Body Style:	Wagon	[Pass	Fail	N/A
Year:	2006	Registration:	HFQ824	Reg Expiry:	08 Oct 2018	Engine			
WoF Expiry:	30 Nov 2018	Odometer:	141,837 Kms	Good No:	18593329	Oil level	~		<u> </u>
VIN:	WVWZZZ3CZ7E09545	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Dauta hava nat	hoon disponstad or	Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			<u> </u>
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	s	-0	S			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	scw 6/6			The	SD SD	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack				$+ \vee$	P SC	Clutch			~
P = pin dent	HID				74 <u>11</u>	CV joints	~		
* = decals	D 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W P P						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread	-	of tyre	<u>ا</u>
Left front Indicator trim loose						Left front 7 m			
						Right front		7	mm
						Left rear		5	mm
Conditions During Rody Inspection:						Right rear			mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
Oil leak	-	·				Suspension performance	~		<u> </u>
AC not gett						Steering performance	~		
Information	n warning light stays on					Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation		~	
Interior Comments						Electrical / Accessories		•	<u> </u>
Seats	Good					Head lights	~		
	Coord					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights		~	
						Wipers (front & rear)	~	-	1
Dashboa	rd Good					Window winder FL	~		
<u> </u>	1				J	Window winder FR	~		1
<u>General</u> (<u>Comments</u>					Window winder RL	~		+
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		1
						CD (basic test only)	~		1
						Number of keys	2		1
Road Con	ditions During Test	- Drive]	Central locking	2 V		
			Dry			Remote locking	~		+
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac		es	Kms: 10	6,651	Reversing camera			~
	-	-							
Inspected by: John Lindsay Date: 08 Oct 2018									
I have read	and understood th	is condition q	uide. Name: .			Signature:			