

Report ID: 18,593,454 Version: 1 08 Oct 2018 Created:

Make:	BMW	Model:	X5	Body Style:	SUV	1		Pass	Fail	N/A	
Year:	2002	Registration: ASZ583 Reg Expiry: 24 Nov 2018		Eng	jine		<u> </u>				
WoF Expiry:	09 Nov 2018	Odometer: 186,676 Kms Good No: 18593454			Oil level						
VIN:	WBAFB32040LN86507	Next Service:	189,000kms	Service Histor	y: Yes	Sr	noke & fumes	~			
						J Pe	erformance	~			
	port is not a warranty	aration is made	for any and milages	Darts have not	been dismonthed or	N	oise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cod	Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							polant condition	~			
						. ⊨	erformance	~			
Key:	sc	-0	SP SP		s	Ra	adiator / Hoses (visual)	~			
S = scratch							nsmission	•			
D = dent R = rurt SC D B S							peration	~			
R = rust PT = paint defect							oise	~			
C = crack				+	SC		utch	•		~	
P = pin dent					세비		/ joints	~			
* = decals	sc 916			-NL	ETP w		heel bearings	· ·			
SC = stone chips							Brakes				
W = significant scuffs SC S W							Performance				
		Note: som	ne defects & blemishes	may not be disr			and Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread depth of tyres			() ()	
Head lights dull. Detachable tow bar.						IĽ					
Fine chips on screen .							Right front		•		
							Left rear		5 r 4 r		
						- I	Right rear		-	mm mm	
Conditions During Body Inspection: Dry											
Under Carriage & Under Bonnet Inspection Comments						1 <u> </u>	Spare Yes Suspension				
Oil leaks .							spension performance	~			
							eering performance	~			
							nock absorbers	v v			
							Conditioning / Heater	v			
						」					
Interior Comments						I - '	Operation Electrical / Accessories				
Average						Head lights					
Seats							ail lights	-			
Carpets	Average						dicators	<u>ィ</u> ィ			
Devision	cargo bline	missing .				ashboard warning lights	v v				
Panels							ipers (front & rear)	v v			
Dashboa	read out n	ot working prop	erly.				indow winder FL	v v			
						」	indow winder FL	V			
General (<u>Comments</u>						indow winder FR		~		
OK,								v			
Drivers window not working, will not go up.							indow winder RR	V 			
							ear view mirrors	V			
							adio (basic test only)	~			
							D (basic test only)			~	
						. —	Number of keys2Central locking				
Road Conditions During Test Drive: Dry							-	~			
Engine Timing Mechanism: Timing Chain							emote locking		~		
Evidence of Cam Belt Replacement: Not Applicable Kms:							at. Nav. (basic test only)			~	
							eversing camera			~	
Inspected by: Daryll Timms Date: 08 Oct 2018											

I have read and understood this condition guide.

Name:

Signature: