

Basic Vehicle Condition Guide

Report ID: 18,593,514


Version:

Created: 08 Oct 2018

Make: Model: Aurion **Body Style:** Sedan Toyota Year: 2007 Registration: DUK412 Reg Expiry: 20 Jul 2019 **WoF Expiry: Odometer: Good No:** 18593514 09 May 2019 255,326 Kms VIN: 6T153KK400X281949 **Next Service: Service History:** 260596 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

08 Oct 2018 Inspected by: Brian Hill Date:

Name:

	_		
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>v</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		3	mm
Right front	6		mm
Left rear		2	mm
Right rear	4		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	!		-
Operation	~		
Electrical / Accessories	I		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	<i>v</i>		
Window winder FL	~		
Window winder FR	-/		
Window winder RL	<i>v</i>		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	·		
Remote locking	<u></u>		
Sat. Nav. (basic test only)	ļ -		1
Reversing camera			<i>y</i>
eversing curnera			

Signature: