

Report ID: 18,593,726


Version:

10 Oct 2018 Created:

| Make:       | Mini             | Model:        | Cooper     | Body Style:    | SUV          |
|-------------|------------------|---------------|------------|----------------|--------------|
| Year:       | 2015             | Registration: | JHG806     | Reg Expiry:    | 28 Feb 2019  |
| WoF Expiry: | 01 Sep 2019      | Odometer:     | 49,925 Kms | Good No:       | 18593726     |
| VIN:        | WMWZB32040WT857. | Next Service: | 51489      | Service Histor | <b>y:</b> No |

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Stone chips front screen.

| Conditions During Body Inspection: Dry | Conditions | During | Body | Inspection: | Drv |
|--|------------|--------|------|-------------|-----|
|--|------------|--------|------|-------------|-----|

**Under Carriage & Under Bonnet Inspection Comments** 

FWD.

| Interior Comments |      |  |
|-------------------|------|--|
| Seats             | Good |  |
| Carpets           | Good |  |
| Panels            | Good |  |
| Dashboard         | Good |  |

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

| Create                              | d: 10  | 0 Oct 2  | 018        |
|-------------------------------------|--|--|------------|
|                                     | Pass   | Fail   | N/A        |
| Engine                              |  |  |            |
| Oil level                           | ~  |  |            |
| Smoke & fumes                       | ~  |  |            |
| Performance                         | \( \times \)   |  |            |
| Noise                               | ~  |  |            |
| Cooling System                      |  |  |            |
| Coolant condition                   | ~  |  |            |
| Performance                         | ~  |  | 1          |
| Radiator / Hoses (visual)           | <b>V</b>   |  |            |
| Transmission                        |  |  |            |
| Operation                           | ~  |  |            |
| Noise                               | ~  |  |            |
| Clutch                              |  |  | \ <u>\</u> |
| CV joints                           |  | <del>                                     </del> | +          |
| Wheel bearings                      | -  |  |            |
| Brakes                              | _  |  |            |
| Performance                         | ·/   |  | Τ          |
| Hand Brake                          | •  |  |            |
| Tyres (lowest observed tread        | denth  | of tyre  |            |
| Left front                          | · ·  | -  | mm         |
| Right front                         |  | .5   | mm         |
| Left rear                           |  | .5   | mm         |
| Right rear                          |  | .5   | mm         |
| Spare                               | /  | .5   | 111111     |
| Suspension                          |  | N/A  |            |
| Suspension performance              |  |  |            |
| Steering performance                |  |  |            |
| Shock absorbers                     | \( \triangle \)  |  |            |
| Air Conditioning / Heater           | <i>V</i>   |  |            |
|                                     |  |  |            |
| Operation  Electrical / Accessories | •  |  |            |
|                                     |  |  |            |
| Head lights                         | •  |  |            |
| Tail lights                         | •  |  |            |
| Indicators                          | \( \triangle \tr |  |            |
| Dashboard warning lights            | •  |  |            |
| Wipers (front & rear)               | ~  |  |            |
| Window winder FL                    | <b>'</b>   |  |            |
| Window winder FR                    | ~  |  |            |
| Window winder RL                    | V  |  |            |
| Window winder RR                    | ~  |  |            |
| Rear view mirrors                   | <b>/</b>   |  |            |
| Radio (basic test only)             | ~  |  |            |
| CD (basic test only)                | ~  |  |            |
| Number of keys                      | 2  |  |            |
| Central locking                     | ~  |  |            |
| Remote locking                      | ~  |  |            |
| Sat. Nav. (basic test only)         |  |  | ~          |

I have read and understood this condition guide.

**Eddie Marsters** 

| Name |  |  |  |
|------|--|--|--|

| Signature |  |
|-----------|--|
|           |  |

Date: 10 Oct 2018

Reversing camera