

Basic Vehicle Condition Guide

Report ID: 18,593,790


Version:

10 Oct 2018 Created:

Make: Model: **BMW** X5 **Body Style:** SUV Year: 2008 Registration: JBY940 Reg Expiry: 21 Oct 2018 Good No: **WoF Expiry: Odometer:** 18593790 10 Apr 2019 77,387 Kms VIN: WBAFE42090LK94297 **Next Service: Service History:** 86000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Both outter taillight lens cracked.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

	Pass	Fail	N/A	
Engine	r ass	ı⁻all	IN/A	
Engine				
Oil level Smoke & fumes				
	\(\times \)			
Performance	-			
Cooling System				
Coolant condition	V V			
Performance	•			
Transmission				
Operation	•			
Noise	-			
Clutch			-	
CV joints	-			
Wheel bearings	'			
Brakes				
Performance	~			
Hand Brake	'		<u> </u>	
Tyres (lowest observed treac		-		
Left front	7	.5	mm	
Right front	7.5		mm	
Left rear	7	.5	mm	
Right rear	7.5		mm	
Spare		N/A		
Suspension			1	
Suspension performance	~			
Steering performance	~			
Shock absorbers	•			
Air Conditioning / Heater				
Operation	•			
Electrical / Accessories		I		
Head lights	V			
Tail lights	'			
Indicators	~			
Dashboard warning lights	\(\triangle \)			
Wipers (front & rear)	~			
Window winder FL	V			
Window winder FR	'			
Window winder RL	~			
Window winder RR	'			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)	~			
Reversing camera			'	
Date: 10 Oct 2018				
Date. 10 Oct 2010				

I have read and understood this condition guide.

Eddie Marsters

Name:

Signature: