

Report ID: 18,594,141


Version:

12 Oct 2018 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility
Year:	2006	Registration:	DJZ910	Reg Expiry:	25 Sep 2019
WoF Expiry:	16 Mar 2019	Odometer:	231,141 Kms	Good No:	18594141
VIN:	MMBJNK6506D03130	Next Service:	234,800kms	Service Histor	<b>y:</b> No

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



### **Body Inspection Comments**

Right side of rear bumper has had a impact & been bent upwards

Conditions During Body Inspection: Wet

## **Under Carriage & Under Bonnet Inspection Comments**

Oil weep from right side & from between engine & gearbox.

Interior Comments				
Seats	Average			
Carpets	Good			
Panels	Good			
Dashboard	Good			

# **General Comments**

Inspected by:

Needs a wheel alignment, as pulling to left.

Radio & cd player not going as need factory security code to get it to work.

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

Jason Young

**Evidence of Cam Belt Replacement:** Kms: No

Date: 12 Oct 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<b>V</b>		
Noise	~		
Cooling System		•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	L es)
Left front		.3	mm
Right front		.8	mm
Left rear		.2	mm
Right rear	•		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	·		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			
	<b>'</b>		
Window winder RR	<b>V</b>		1
Window winder RR  Rear view mirrors	~		
Rear view mirrors			
Rear view mirrors Radio (basic test only)	~	V	
Rear view mirrors Radio (basic test only) CD (basic test only)	<i>V</i>	<i>V</i>	
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	1	<i>V</i>	
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	<i>V</i>	<i>V</i>	
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking	1	<i>V</i>	<i>V</i>
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	1	<i>V</i>	V V

I have read and understood this condition guide.

Name: .....

Signature: .....