

Report ID: 18,594,253 Version: 2 22 Mar 2019 Created:

Signature:

Make: Volvo Model: XC90 Body Style: SUV	Pass	Fail	N/A
Year: 2005 Registration: HKE488 Reg Expiry: 17 Apr 2019 Engine	Engine		
WoF Expiry: 31 Oct 2019 Odometer: 194,623 Kms Good No: 18594253 Oil level	v		
VIN: YV1CZ914851143638 Next Service: 204599 Service History: No Smoke & f	fumes 🖌		
Performan	nce 🖌		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends	stem		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	ondition 🖌		
Your S S S SPSC S SSC Performan	nce 🖌		
Rey. Radiator /	/ Hoses (visual) 🖌		
S = scratch	ion		
D = dent R = rust S Operation	n 🖌		
PT = paint defect Noise	~ ~		
C = crack			~
P = pin dent	~		
* = decals SC OID S Wheel bea			
SC = stone chips	•		
W = significant scuffs SC S S SC S SC S SC Performan	nce 🖌		
Note: come defects & blemiches may not be displayed in the diagram	•		
Body inspection Comments	est observed tread depth	of tyre	s)
Moisture inside the LR tail light ,			
Right from			mm
Left rear			mm
			mm
Conditions During Body Inspection: Dry Right rear		.0 Yes	
Under Carriage & Under Bonnet Inspection Comments Suspension		res	
	on performance 🖌		
	performance V		
Shock abs	•		
	-		
Air Conditioning / Heater			
	Accessories		
Lieu Rair,			
Seats			
Carpets wear and tear,minor stains ,			
Indicators	· ·		
Panels	d warning lights	~	
Dashboard Average	ront & rear)		
General Comments Window v			
Hood living needs repair brand new battery			
	•		
Rear view			
	sic test only) 🖌		
CD (basic			~
Number o		,	
Road Conditions During Test Drive: Dry Central lo	cking 🖌		
Remote lo	-		
	(basic test only)		~
Evidence of Cam Belt Replacement: Yes Kms: 152,625	l camera		~
Reversing			
	Date: 28 Nov 2018		

I have read and understood this condition guide.

Name: