

Report ID: 18,594,403 Version: 1 10 Oct 2018 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	DFC60	Reg Expiry:	27 Nov 2018	Engine			L
l	15 Mar 2019	Odometer:	198,564 Kms	Good No:	18594403	Oil level	~		
VIN:	JSAEZC21S00151219	Next Service:	182000	Service Histor		Smoke & fumes	~		
	55					Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismontiad as						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	S P SC	-0	S P SC S P SC		S D	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			T	Transmission	•		
D = dent	SDCSC			The		Operation	~		
R = rust				10	JHIA	Noise	~		
PT = paint def C = crack				+	S SC	Clutch	~		~
P = pin dent	Ho	KI			JUII —	CV joints	~		
* = decals	SDSC PR			AL.	FINA T	Wheel bearings	-		
SC = stone chips							~		
W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<i>с</i> .	Ļ
Has different wheels all round ,						Tyres (lowest observed tread depth of tyres)			
						Left front		2	mm
						Right front		2	mm
[Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	1	2	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & Under BOI	met inspectic	on comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd glove box	broken,air vents	broken ,			Wipers (front & rear)	~		
	iu					Window winder FL	~		
	-					Window winder FR	~		
General Comments						Window winder RL	~		
When putti	ng drivers window up r	nakes a winding	noise ,			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						L			
Inspected by: Donovan Matara Date: 10 Oct 2018									
I have read and understood this condition guide. Name:									