

Report ID: 18,594,572 Version: 1 Created: 08 Oct 2018

| Make: | Jeep | Model: | Grand Cherokee | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|---------------------------------------|----------------------|------------------------------|---------|---------|------------|
| Year: | 2007 | Registration: | EFH830 | Reg Expiry: | 11 Nov 2018 | Engine | 1 | | |
| WoF Expiry: | 07 Jul 2019 | Odometer: | 142,143 Kms | Good No: | 18594572 | Oil level | ~ | | |
| VIN: | 1J8HD58265Y549553 | Next Service: | 146990 | Service Histor | y: Yes | Smoke & fumes | V | | |
| | | | | | | Performance | V | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismontled or | Noise | V | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | nis can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | SC | -0 | SC | -01- | s | Radiator / Hoses (visual) | V | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| D = dent R = rust | sc | | | 715 | SC SC | Operation | ~ | | |
| PT = paint defe | | r I | | $\left(\left \right\rangle \right)$ | | Noise | V | | |
| C = crack | | | | + | SC | Clutch | | | ~ |
| P = pin dent | HIG | | | | 게 | CV joints | V | | |
| * = decals | sc 91 | | | -No- | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SC | | | | | | Performance | ~ | | |
| Padulaa | action Commonts | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| Stone chips front screen. | | | | | | Left front | | | mm |
| | | | | | | Right front | | | mm |
| | | | | | | Left rear | | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7 mm | | |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | V | | |
| Carpets | Guou | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | V | | |
| | | | | | | Radio (basic test only) | V | | |
| | | | | | | CD (basic test only) | V | | |
| | | | | | | Number of keys | 2 | | L |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | | | _ - |
| Inspected by: Brian Hill Date: 08 Oct 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: