

Report ID: 18,594,689 Version: 1 Created: 09 Oct 2018

Make:	Mitsubishi	Model:	Mirage	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1998		XA1836	Reg Expiry:	28 Oct 2018	Engine			L
WoF Expiry:	29 Dec 2018	Odometer:	97,498 Kms	Good No:	18594689	Oil level	~		
VIN:	JMFMRCJ2AVU002884	Next Service:	<i>57</i> ,150 Kills	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta harra nat	harry discounted as	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	sc	-0	P SC		PT SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation		~	
R = rust				10	JHIN	Noise	~	V	
PT = paint defe C = crack				+	PT SC	Clutch	V		~
P = pin dent	Ho				JUII —	CV joints	~		
* = decals	D PT SC D P				Ell'As	· ·			
SC = stone chips						Wheel bearings	~		
W = significant scuffs P SC W S P W S P						Brakes			
Noto: come defecte % blamiches may not be displayed in the dispran						Performance			~
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<b>6</b> .	Ļ
Clearcoat is coming off vehicle. Bad paint repairs on bonnet and roof. Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			
CD holder in console not staying shut. LH pivot on parcel tray is damaged.						Left front 5			mm
						Right front		5	mm
						Left rear		5 mm	
Conditions During Body Inspection: Dry						Right rear	6 mm		
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	1	-	1
Some surfa	ce rust under floor.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation			~
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average				Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ra -					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			<
Transmissic	on flaring from 1st to 2n	d gear.				Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		-			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 61	,044	Reversing camera			~
						<b></b>			
Inspected by: Roger King Date: 09 Oct 2018									
I have read and understood this condition guide. Name:									