

# **Basic Vehicle Condition Guide**

Report ID: 18,594,852


Version:

Created: 31 Oct 2018

Make: Model: Volkswagen **Body Style:** Transporter Van Year: Registration: Reg Expiry: 2006 LRM496 11 Nov 2018 WoF Expiry: **Odometer:** 01 May 2019 **Good No:** 18594852 168,596 Miles VIN: **Next Service: Service History:** WV1ZZZ7HZ7H04231 174,000 miles No

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



#### **Body Inspection Comments**

Interior mirror missing

FL door inner handle trim missing, RH insecure

FR door misaligned

Tailgate left door stopper missing

Fuel door misaligned

Conditions During Body Inspection: Dry

### **Under Carriage & Under Bonnet Inspection Comments**

Underbody surface rust RH CV boot minor leak

<u>Interior Comments</u>					
Seats	Average				
Carpets	Average				
Panels	Average				
Dashboard	Average				

## **General Comments**

Jerk while shifting gear, transmission mounting needs attention FR park light not working

Road Conditions During Te

Road Conditions During Test Drive: Dry	Certifal locking				
,		Remote locking		~	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Yes	Kms: 158,000	Reversing camera			~
Inspected by: Mathew Varghese		Date: 15 Oct 2018			
I have read and understood this condition guide.	Name:	Signature:			

		Pass	Fail	N/A					
	Engine								
	Oil level	~							
	Smoke & fumes	<b>V</b>							
1	Performance	/							
	Noise	~							
	Cooling System								
	Coolant condition	~							
	Performance	~							
	Radiator / Hoses (visual)	/							
	Transmission								
	Operation	~							
	Noise	/							
	Clutch	> > >							
	CV joints	~							
	Wheel bearings	/							
	Brakes								
	Performance	~							
	Hand Brake	~							
	Tyres (lowest observed tread	depth	of tyre	es)					
	Left front	5	.0	mm					
	Right front	5	.0	mm					
	Left rear	2.0		mm					
	Right rear	2.0		mm					
] ]	Spare		Yes						
	Suspension								
	Suspension performance	~							
	Steering performance	<b>V</b>							
	Shock absorbers	>							
	Air Conditioning / Heater								
1	Operation			~					
	Electrical / Accessories								
	Head lights	~							
	Tail lights	~							
	Indicators	>							
	Dashboard warning lights	<b>'</b>							
	Wipers (front & rear)	> > > > > > > > > > > > > > > > > > >							
	Window winder FL	~							
]	Window winder FR	~							
	Window winder RL			~					
	Window winder RR			V					
	Rear view mirrors	>							
	Radio (basic test only)	<b>'</b>							
	CD (basic test only)	~							
]	Number of keys	1							
	Central locking	<b>&gt;</b>							
, ]	Remote locking		~						
	Sat. Nav. (basic test only)			~					
	Reversing camera			<b>'</b>					
	<u></u>								