

Report ID: 18,594,984 Version: 2 12 Oct 2018 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	JHP152	Reg Expiry:	10 Mar 2019	Engine			
WoF Expiry:	04 Sep 2019	Odometer:	126,025 Kms	Good No:	18594984	Oil level	~		
VIN:	7AT0DH78X15110096	Next Service:	133528	Service Histor		Smoke & fumes	~		
						Performance	V		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0		-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	sc w			715	HILW	Operation	~		
PT = paint def		F		$\left( \left  \left( \right) \right\rangle \right)$		Noise	V		
C = crack					SC	Clutch			~
P = pin dent	HID				74114	CV joints	V		
* = decals	sc 916			-NG		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S W S W						Performance	V		
Podulaci	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection comments						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
Stone chips front screen. Right rear quarter panel trim broken. Right front mudflap not secure								mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear		.0	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	V		
						Air Conditioning / Heater	I		I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
<u> </u>	Good					Tail lights	~		
Carpets	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	L					Window winder FR	~		
<u>General</u> (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	V		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			- ' y			Remote locking	~		
-	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 09 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....