

Basic Vehicle Condition Guide

Report ID: 18,596,026


Version: 2

Created: 10 Oct 2018

Make: Model: Mazda **Body Style:** SUV Premacy Year: 2007 Registration: KCB776 Reg Expiry: 22 Mar 2019 WoF Expiry: **Odometer: Good No:** 03 Aug 2019 129,037 Kms 18596026 VIN: **Next Service: Service History:** 7AT0C133X16169333 135300

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RH sliding door not shutting fully by itself. Stonechips on windscreen. Remote locking not working.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front brake pads low.

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Kms: Not Applicable

10 Oct 2018 Inspected by: Roger King Date:

Name:

| | D | F - 11 | NI/A | |
|-----------------------------------|--------------|---------|------|--|
| Engino | Pass | Fail | N/A | |
| Engine Oil level | | | | |
| Smoke & fumes | - | | | |
| | \(\times \) | | | |
| Performance Noise | <i>V</i> | | | |
| | <i>V</i> | | | |
| Cooling System Coolant condition | | | | |
| Performance | <i>V</i> | | | |
| | • | | | |
| Radiator / Hoses (visual) | | | | |
| | | | 1 | |
| Operation | • | | | |
| Noise | - | | _ | |
| Clutch | | | - | |
| CV joints | - | | | |
| Wheel bearings | ~ | | | |
| Brakes | ı | I | I | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | : | 5 | mm | |
| Right front | 4 | | mm | |
| Left rear | 3 | | mm | |
| Right rear | 3 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | V | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | v v | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | <i>'</i> | | | |
| Window winder FL | <i>'</i> | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ' | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | | ~ | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | | | |

Signature: