

Report ID: 18,596,799 Version: 1 Created: 09 Oct 2018

Make:	BMW	Model:	5 Series	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2006	Registration:	LQS462	Reg Expiry:	16 Mar 2019	Engine	1	I		
WoF Expiry:	01 Oct 2019	Odometer:	29,595 Kms	Good No:	18596799	Oil level	~			
VIN:	WBANE52000CK68608	Next Service:	40000	Service Histor	V: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:		-0		500-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission			1	
R = rust	sc			210		Operation	~			
PT = paint def	ect NP					Noise	~			
C = crack				TTY .		Clutch			~	
P = pin dent	HR				2416	CV joints			~	
* = decals	- dle	10		10	S PT	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W = significan	W					Performance	~			
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
<u></u>						Tyres (lowest observed tread depth of tyres)				
					Left front	4	1	mm		
						Right front	5	5	mm	
						Left rear	7	7	mm	
Conditions During Body Inspection: Dry						Right rear	7 mm			
						Spare No				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Clean						Suspension performance	~			
						Steering performance	~			
Shock absc							~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
Dastibua						Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2	1		
Road Conditions During Test Drive: Dry						Central locking	~			
F actor 7 1						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspector	Inspected by: Stuart Melbourne Date: 09 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: