

Basic Vehicle Condition Guide

Report ID: 18,596,850


Version:

Created: 16 Oct 2018

Make: Model: Holden Berlina **Body Style:** Sedan Year: 2003 Registration: DGB569 Reg Expiry: 30 Mar 2019 **WoF Expiry: Odometer:** 14 Sep 2019 **Good No:** 18596850 105,508 Kms VIN: 6G1YL54AX3L979437 **Next Service: Service History:** 110000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Coolant condition fail Bonnet gas strut not working

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

Dry

General Comments

AC not working

Remote key cover need attention

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 16 Oct 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition		~	
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			_
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		5	mm
Right front		3	mm
Left rear	3		mm
Right rear	4		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation		~	
Electrical / Accessories		· ·	
Head lights	V		
Tail lights	V		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	<i>y</i>		
Window winder FL	\(\times \)		
Window winder FR	1/		
Window winder RL	<i>V</i>		
Window winder RR	~		
Rear view mirrors			
	<i>V</i>		
Radio (basic test only)	V		-
CD (basic test only)	~		
Number of keys	2		1
Central locking	<i>'</i>		
Remote locking	-		<u> </u>
Sat. Nav. (basic test only)			'
Reversing camera			

I have read and understood this condition guide.

Name:

Signature: