

Report ID: 18,596,897 Version: 1 10 Oct 2018 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	LPG978	Reg Expiry:	29 Jan 2019	Engine			
WoF Expiry:	21 Jun 2019	Odometer:	167,586 Kms	Good No:	18596897	Oil level	~		
VIN:	7AT0C13JX16202050	Next Service:	162000	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0			<u>SD</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sscw			715	SDW	Operation	~		
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				74 <u>11</u>	CV joints	~		-
* = decals R SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W D W						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tvres (lowest observed tread	Tyres (lowest observed tread depth of tyres)		
Roof rack mount covers missing Left side wing mirror cracked									mm
	5					Right front		5 4	mm
						Left rear			mm
Conditions During Pody Inspection, D					Right rear			mm	
Conditions During Body Inspection: Dry						Spare	<u> </u>		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at worn				Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators		~	
Danala	Average					Dashboard warning lights	~	•	
Panels						Wipers (front & rear)	~		
Dashboa	Ird AC panel I	oose, informatior	n screen missing			Window winder FL	~		
						Window winder FR	~		
General C	Comments					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	· ·		
Koad Con	attions During Tes	u Drive:	Dry			Remote locking	v v		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	-		~
-	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~
	-1								•
Inspected by: John Lindsay Date: 10 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....