

Report ID: 18,597,011 Version: 1 10 Oct 2018 Created:

Make:	Toyota	Model:	Avensis	Body Style:	Sedan		Pass	Fail	N/A
Year:	2004	Registration:	JGC909	Reg Expiry:	05 Feb 2019	Engine	I	1	1
	24 Aug 2019	Odometer:	125,177 Kms	Good No:	18597011	Oil level	~		
VIN:	7AT0H63MX15023519	Next Service:	not known	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S	-0		-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes	V		L
W = significant scuffs SD W SD						Performance			
						Hand Brake			
body inspection comments							• • • • • •		
Stone chips front screen. Unable to adjust left mirror. Dash cracked						Tyres (lowest observed tread depth of tyres)			
						Left front 6			mm
						Right front		5	mm
						Left rear		1	mm
Conditions During Body Inspection: Wet						Right rear		5	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Engine cover cracked						Suspension	L .		1
Engine cov	er cracked					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			1
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Poor					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
La constata di la constata di 1911							10		
Inspected by: Brian Hill Date: 10 Oct 2018									
I have read and understood this condition guide. Name:									