

Report ID: 55,150 Version: 1 Created: 02 Nov 2018

Make:	Ford	Model:	Focus	Body Style:	Hatchback	][		Pass	Fail	N/A	
Year:	2009	<b>Registration:</b>	EUS267	<b>Reg Expiry:</b>	07 Apr 2019	ī	Engine	L	1		
WoF Expiry:	21 Dec 2018	Odometer:	158,319 Kms	Good No:	18597654	ļŀ	Oil level	~			
VIN:	WF0PXXGCDP8S0316	Next Service:	-	Service Histor	<b>y:</b> No	ļŀ	Smoke & fumes	~			
						it	Performance	~			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	ļŀ	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	narge.	lļ	Coolant condition	~			
						1ľ	Performance	~			
Key:		-0		500-		lf	Radiator / Hoses (visual)	~			
S = scratch D = dent						lŀ	Transmission		1		
D = dent R = rust				710	HIVS	lŀ	Operation	~			
PT = paint defe	ect NP	r I		$\left( \left  \left( \right) \right\rangle \right)$	70H	lŀ	Noise	~			
C = crack						lŀ	Clutch			~	
P = pin dent	HIG				74114	lŀ	CV joints	~			
* = decals	- Alt			-Jos	ED S	lŀ	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs						lŀ	Performance	~			
Bodylas		Note: son	ne defects & blemishes	s may not be disp	blayed in the diagram	lŀ	Hand Brake	<b>v</b>			
Body Inspection Comments						ļŀ	Tyres (lowest observed tread depth of tyres)				
						lŀ	Left front		4	mm	
							Right front		4	mm	
						Jŀ	Left rear		4	mm	
Conditions During Body Inspection: Dry						1ŀ	Right rear 4			mm	
Conditions During Body Inspection: Dry						ļŀ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension	<u> </u>			
							Suspension performance	~			
						lŀ	Steering performance	~			
						lŀ	Shock absorbers	~			
							Air Conditioning / Heater	L	1	1	
L							Operation	~			
Interior Comments						ī	Electrical / Accessories				
Seats	Good					ļŀ	Head lights	~			
	Good					ļŀ	Tail lights	~			
Carpets						ļŀ	Indicators	~			
Panels	Good						Dashboard warning lights	~			
	, Good						Wipers (front & rear)	~			
Dashboa	rd						Window winder FL	~			
	1					ł	Window winder FR	~			
General Comments						ļŀ	Window winder RL	~			
						ļŀ	Window winder RR	~			
						lŀ	Rear view mirrors	~			
						lŀ	Radio (basic test only)	~			
						ļŀ	CD (basic test only)	~			
						Jŀ	Number of keys	1	1	1	
Road Conditions During Test Drive: Dry						۱ŀ	Central locking	~			
						ļŀ	Remote locking	~			
Engine Timing Mechanism: Timing Chain						lŀ	Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~	
									1		
Inspected by: Scott Date: 30 Oct 2018											

I have read and understood this condition guide.

Name: .....