

Basic Vehicle Condition Guide

Report ID: 18,597,872


Version:

Created: 11 Oct 2018

Make: Model: **Body Style:** Wagon Honda Odyssey Year: Registration: Reg Expiry: 2004 LDJ891 11 Jul 2019 WoF Expiry: **Odometer:** 03 Jan 2019 **Good No:** 18597872 100,963 Kms VIN: 7AT08G61X17062221 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Dent all over bonnet, dents down left rear door, left rear guard & left rear side of rear bumper. Scratches & scuffs along right side sill. Has lower suspension springs & shocks.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

11 Oct 2018 Inspected by: Jason Young Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|----------------------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | v v | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | | • | |
| Coolant condition | ~ | | | |
| Performance | <i>V</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | > | | | |
| Noise | ' | | | |
| Clutch | | | ~ | |
| CV joints | > | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 3.7 | | mm | |
| Right front | 3.5 | | mm | |
| Left rear | 3.4 | | mm | |
| Right rear | 4.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | 1 | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | 1 | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | ı | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | V V V V V V | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | 1 | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | | |

Signature: