

Basic Vehicle Condition Guide

Report ID: 18,598,906


Version: 4

Created: 17 Jan 2019

Make: BMW Model: 1 Series **Body Style:** Hatchback Year: 2006 Registration: JMS583 Reg Expiry: 06 Jun 2019 WoF Expiry: **Odometer:** 19 Nov 2019 89,560 Kms **Good No:** 18598906 VIN: WBAUF12070PZ32087 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Front badge missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Poor		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 17 Jan 2019

Name:

	Pass	Fail	N/A
Engine			1
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		5	mm
Right front		5	mm
Left rear	:	2	mm
Right rear	2		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			!
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	/		
Window winder RR	v		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	<u> </u>	1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	-		V
Reversing camera			1

Signature: