

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments Oil leak

		Air Conditioning / Heater	Air Conditioning / Heater		
		Operation	~		
Interior Comments		Electrical / Accessories	Electrical / Accessories		
Seats	Good	Head lights	~		
Carpets	Good	Tail lights	~		
		Indicators	~		
Panels	Average	Dashboard warning light	is 🖌		
Dashboard	Good	Wipers (front & rear)	~		
		Window winder FL	~		
		Window winder FR	~		
General Comments		Window winder RL	~		
		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		

CD (basic test only) ~ Number of keys 2 V Central locking Road Conditions During Test Drive: Dry Remote locking V **Engine Timing Mechanism:** Unknown Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Kms: Not Applicable Reversing camera ~

Inspected by: Donovan Matara

15 Oct 2018 Date:

Left rear

Right rear

Suspension

Suspension performance

Steering performance

Shock absorbers

Spare

I have read and understood this condition guide.

Name:

Signature:

N/A

V

mm

mm

mm

mm

3

3

V

V

~

Yes