

Report ID: 18,600,020 Version: 1 17 Oct 2018 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	HQQ173	Reg Expiry:	07 Sep 2019	Engine	I		L
WoF Expiry:	09 Aug 2019	Odometer:	61,823 Kms	Good No:	18600020	Oil level	~		
VIN:	JM0BM547810132892	Next Service:		Service Histor		Smoke & fumes	~		
			•			Performance	~		
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	LS			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			210	HIVS	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7411L	CV joints	~		
* = decals	sc all			10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – signinican	DW					Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	.3	mm
						Right front	5.	.4	mm
						Left rear	6.	.5	mm
Conditions During Body Inspection: Dry Right rear						Right rear	7.	.1	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry									
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Ian Dunn Date: 17 Oct 2018									
Inspected by. Ian Dunin Date: 17 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: