

Report ID: 18,600,451 Version: 1 Created: 15 Oct 2018

Make:	Skoda	Model:	Octavia	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011	Registration:	FWN564	Reg Expiry:	02 Aug 2019	Engine	I	l	1
WoF Expiry:	11 Jul 2019	Odometer:	139,253 Kms	Good No:	18600451	Oil level	~		
VIN:	TMBCT61Z1B2125424	Next Service:	unknown	Service Histor		Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	S P SC W		SC	Radiator / Hoses (visual)	~		-
S = scratch							Transmission		
D = dent						Operation		~	
R = rust PT – paint def				\prod	JHIH	Noise	~	•	
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		-
* = decals SC Q Q						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D SC W S S S W S						Performance 🖌			
Noto: come defecte % blamiches may not be displayed in the displayer						Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread	•	oftvre	1 2s)
Chipped screen. One number plate light out .						Left front 4 mm			
						Right front			mm
						Left rear		5	mm
						Right rear		, 1	mm
Conditions During Body Inspection: Dry						Spare	2	-	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Tidy.						Suspension performance	~		1
nay.						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
									1
Interior Comments						Operation Electrical / Accessories	~		
Δυργορο						Head lights			
Seats							~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments Slight trans flare at low speed, & possibly needs mounts.						Window winder RL	~		
		,				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
LYNGENCE	or cam beit nepiac	cincili. N	lo	11113.		Reversing camera			~
Inspecte	Date: 15 Oct 2018								
I have read and understood this condition guide. Name:									