

Report ID: 18,601,048 Version: 1 04 Dec 2018 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility][]	Pass	Fail	N/A
Year:	2013	Registration:	HDF452	Reg Expiry:	07 May 2019	Engine			L
WoF Expiry:		Odometer:	126,673 Kms	Good No:	18601048	Oil level		~	
VIN:	MR0FZ22G901079069	Next Service:	-,	Service Histor	y: No	Smoke & fumes	~	-	
					-	Performance	~		
	port is not a warranty	oration is made	for and mileage	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	iical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		$- \square$		Radiator / Hoses (visual)	r		
S = scratch D = dent						Transmission			
D = dent R = rust	sc			715	HILLS	Operation	~		
PT = paint defe	ect NP	r I		$\left[\left(\right) \right]$	70141	Noise	~		
C = crack						Clutch	~		
P = pin dent	sc dl			$\langle \rangle$	74116	CV joints	~		
* = decals		10		10	ED -	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan			D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Fog light covers missing						Tyres (lowest observed tread depth of tyres)			2s)
Lower grill slates cut out						Left front	5 mm		
						Right front	4	1	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No oil						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Marks on rear seat						Electrical / Accessories			
Seats	Marks on r	ear seat				Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concret	Commonts					Window winder FR	~		<u> </u>
General	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		-
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Mechanism:	Cambelt				Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Lvidence			10	11115.		Reversing camera			~
Inspected	d by: John Lindsay					Date: 04 Dec 20	18		
	. ,								

I have read and understood this condition guide.

Name: