


Report ID: 18,601,105

Version:

16 Oct 2018 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility
Year:	2015	Registration:	JKC214	Reg Expiry:	12 Jan 2019
WoF Expiry:	13 Oct 2018	Odometer:	34,142 Kms	Good No:	18601105
VIN:	MMAJYKK10GH00915	Next Service:	42000	Service History	<b>/:</b> Yes



Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

Inspected by: Stuart Melbourne

I have read and understood this condition guide.

	Radio (basic test only)	<b>/</b>				
	CD (basic test only)	~				
	Number of keys	2				
	Central locking	~				
	Remote locking	~				
	Sat. Nav. (basic test only)		~			
Kms:	Reversing camera	~				
Date: 16 Oct 2018						
Name: Signature:						

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JKC214	Reg Expiry:	12 Jan 2019	Engine			
WoF Exp	iry: 13 Oct 2018	Odometer:	34,142 Kms	Good No:	18601105	Oil level	~		
VIN:	MMAJYKK10GH00915	Next Service:	42000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		1
	<u>lis report is not a warranty</u> ort is a guide only. Consid		for age and mile	eage Parts have not	heen dismantled o	Noise	~		
diagnost	tic testing undertaken. The	vehicle has been	n driven up to 50	km/h from cold. The '	Vendor recommends			-	
a full me	chanical inspection prior to	purchase and t	his can be arrang	ed for an additional c	harge.	Coolant condition	V		
						Performance	·		+
Key:		$-\infty$		$\pm \infty$		Radiator / Hoses (visual)	·		
S = scratc	h Ne				Ser .	Transmission	1 -		
D = dent	sc 6/6				BID _	Operation	V		T
R = rust	7111				JHIH	Noise	V		$\vdash$
PT = pain C = crack	I FII	_		+		Clutch	+		\ <u>\</u>
P = pin de	1 1116		\ <i>!</i> !			CV joints	·		+
· • = decals					HIP.	Wheel bearings	+ -		+-
SC = ston	e chips						<b>'</b>		
W = signi	ficant scuffs			$\pm 0$	$\rightarrow$	Brakes	Τ.,		T
						Performance	<b>'</b>		-
<u>Body</u>	Inspection Comments	Note: son	ne defects & blem	nishes may not be disp	layed in the diagram		<b>'</b>		<u> </u>
						Tyres (lowest observed trea	d depth	of tyre	es) 
						Left front	4	4	mm
						Right front		5	mm
						Left rear	4	4	mm
Cond	itions During Body Ins	pection:	Dry			Right rear		4	mm
		-				Spare		Yes	
<u>Unde</u>	r Carriage & Under Bor	nnet Inspection	on Comments			Suspension	-		
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		1
						Air Conditioning / Heater			
						Operation	V		Τ
<u>Interi</u>	or Comments					Electrical / Accessories			
Seat	Good					Head lights	V		Т
Jeac						Tail lights	\ <u>\</u>		+
Carp	ets					Indicators	+ -		-
_	Good						<i>'</i>		-
Pane	els					Dashboard warning lights	-		-
Dasł	nboard					Wipers (front & rear)	~		-
						Window winder FL	~		
Cana	val Camananta					Window winder FR	~		_
Gene	ral Comments					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road	Conditions During Tes	t Drive:	Dry			Central locking	~		T
			ار ا			Remote locking	~		T
Engin	e Timing Mechanism:	Cambel	t			Sat. Nav. (basic test only)	1		\ <u>\</u>
Evidence of Cam Belt Replacement: No Kms:					Reversing camera	~		Ť	