

Basic Vehicle Condition Guide

Report ID: 18,601,198


Version:

Created: 12 Oct 2018

Make: Model: Dodge Journey **Body Style:** SUV Year: Registration: Reg Expiry: 2016 JYL12 28 Jan 2019 WoF Expiry: **Odometer: Good No:** 03 Feb 2019 18601198 34,727 Kms VIN: 3C4PDCJB0ET185889 **Next Service: Service History:** 42,792 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 12 Oct 2018

Name:

	Pass	Fail	N/A	
Engine		1		
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	ر ا			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes			_	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	8.3		mm	
Right front	8.2		mm	
Left rear	8.7		mm	
Right rear	8.8		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	V V V V V			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature: