

Report ID: 18,601,727 Version: 1 15 Oct 2018 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2003	Registration:	FJU11	Reg Expiry:	03 Dec 2018	Engine			1
WoF Expiry:	27 Jul 2019	Odometer:	189,982 Kms	Good No:	18601727	Oil level	~		
VIN:	7AT0C139X10106067	Next Service:	193438	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0			P SC	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			1
D = dent R = rust	w AR			210	HIVDW	Operation	~		
PT = paint defe		F I		$\left[ \left( \right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP			$\langle \rangle$	74 <u>11</u> 4	CV joints	~		
* = decals	sc 916	1		TA		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – significan	D W				DW	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Stone chips front screen. Tailgate rubber torn. No cargo blind. Doorglass rubbers worn out.					Tyres (lowest observed tread	d depth	of tyre	es)	
					Left front	3 mm			
						Right front	4 mm		mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	<b>-</b>	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 15 Oct 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....