

Report ID: 18,601,961 Version: 1 Created: 21 Oct 2018

Make:	Mercedes-Benz	Model:	C200	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	KOD942	Reg Expiry:	31 Dec 2018	Engine			1
	11 May 2019	Odometer:	82,672 Kms	Good No:	18601961	Oil level	~		
VIN:	WDC2030422R244266		95,325	Service Histor		Smoke & fumes	~		
	WDC2030422R24420C		93,323		9. NO	Performance	~		
	port is not a warranty					Noise			
This report is	a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or		~		
	ical inspection prior to					Cooling System	L .		1
						Coolant condition	~		<u> </u>
Key:	S		S S	W		Performance	~		
S = scratch	2	(0)		(0)	\checkmark	Radiator / Hoses (visual)	~		
						Transmission			
R = rust	sc 96				HIV	Operation	~		
PT = paint def	ect N					Noise	~		
C = crack						Clutch			~
P = pin dent	sc dl				~HHS	CV joints			~
* = decals		10		10	EP S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
RH wing mirror indicator not working						Tyres (lowest observed tread	d depth	of tyre	25)
Driver's seat head rest adjustment not working						Left front 3 mr			mm
LH quarter	panel chrome trim miss	ing				Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		, 5	mm
Conditions During Body Inspection: Dry						Spare	<u> </u>		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	•	·				Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats						Head lights	~		-
Carpets	Good					Tail lights	~		<u> </u>
	Gearleyer	boot insecure				Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
	<u> </u>					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1		<u> </u>
Inspected by: Mathew Varghese Date: 21 Oct 2018									
I have read and understood this condition guide. Name:									