

Report ID: 18,602,207 Version: 1 17 Oct 2018 Created:

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	1996	Registration:	DWJ971	Reg Expiry:	15 Jan 2019	Engine		-	
WoF Expiry:	06 Apr 2019	Odometer:	151,818 Kms	Good No:	18602207	Oil level	~		
VIN:	7A88G610707202771	Next Service:		Service History		Smoke & fumes	~		
	///////////////////////////////////////		139000		110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	S S		s	Radiator / Hoses (visual)	~		
S = scratch	STO	A CO		10c	X	Transmission	v		
D = dent	s sc				BI SDPT	Operation	~		
R = rust				10	JHH	Noise	~		
PT = paint def C = crack	ect M			+	S PT SC	Clutch	V		~
P = pin dent	Htc	KI			JUII ——	CV joints	~		V
* = decals	sc PIC			AL-	EL SP	Wheel bearings	-		
SC = stone chips						Brakes	~		
W = significant scuffs S PT W S PT S S D R									
						Performance	~		
Body Ins	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		<i>C</i> .	Ļ
Stone chips on front windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	5	5	mm
						Right front	5	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil l	eak					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
lusterier C						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	iiu j					Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
Wing mirro	r not working					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 96,212						Reversing camera			~
ч Г							1		
Inspected by: Xinghui Lin Date: 17 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: