

Basic Vehicle Condition Guide

Report ID: 18,602,253


Version:

Created: 15 Oct 2018

Make: Model: Volkswagen Polo **Body Style:** Hatchback Year: Registration: WI7499 Reg Expiry: 1997 14 Oct 2018 WoF Expiry: **Odometer:** 01 Feb 2019 **Good No:** 18602253 161,389 Kms VIN: WVWZZZ6NZVY12763 Next Service: **Service History:** 170000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Front bumper iron rust Gearbox oil leak

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	console plastic broken ,l/f door rubber torn		
Dashboard	Average		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No Kms:

Inspected by: Greg Morgan Date: 15 Oct 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\triangle \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	\(\sigma \)		
Transmission	ı		1
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	5	.5	mm
Right front			mm
Left rear		.5	mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	ļ		
Operation			V
Electrical / Accessories	l		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)			
Window winder FL	\(\times \) \(\t		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2	I	-
Central locking	~		
Remote locking			~
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: