

Report ID: 18,603,532

Version:

Engine

Oil level

Created: 16 Oct 2018

Pass


N/A

Fail

Make: Model: T5 **Body Style:** Volkswagen Van Year: Registration: **Reg Expiry:** 2010 FFH838 30 Jan 2019 WoF Expiry: **Odometer: Good No:** 15 Jun 2019 197,694 Kms 18603532 VIN: **Next Service: Service History:** WV1ZZZ7HZ9H16082 198,000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

Name:

Smoke & fumes ~ Performance ~ Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch V CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 4.7 Left rear 5.9 mm Right rear mm 6.5 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories Head lights** Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR ~ Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

Signature:

Inspected by:	lan Dunn	Date:	16 Oct 2018
---------------	----------	-------	-------------