

Basic Vehicle Condition Guide

Report ID: 18,604,299


Version: 2

Created: 24 Nov 2018

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2014 Registration: HTH664 Reg Expiry: 16 May 2019 WoF Expiry: **Odometer: Good No:** 31 Oct 2019 71,915 Kms 18604299 VIN: 6G1FA5E50EL009565 Next Service: 71,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Small stone crack in right side of windscreen.
- Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\triangle \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	V V			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints			~	
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	es)	
Left front	6	.0	mm	
Right front	6.0		mm	
Left rear	7.0		mm	
Right rear	7.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	1			
Dashboard warning lights	\(\tau \)			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	./			
Window winder RL	<i>v</i>			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	V			
CD (basic test only)	~			
Number of keys	2			
Central locking	<i>V</i>			
Remote locking	<i>V</i>			
Sat. Nav. (basic test only)			./	
Reversing camera	~			
eversing curriera				
Dete: 17.0 ± 2010				

I have read and understood this condition guide.

Jason Young

Name:

Signature:

Date: 17 Oct 2018