

## **Basic Vehicle Condition Guide**

Report ID: 18,604,441


Version: 3

Created: 11 Dec 2018

Make: Model: Volkswagen Golf **Body Style:** Hatchback Year: 2010 Registration: FRC679 Reg Expiry: 22 May 2019 WoF Expiry: **Odometer: Good No:** 25 Oct 2019 248,770 Kms 18604441 VIN: WVWZZZ1KZBW0932 Next Service: 255,000kms Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Right side under sill dented

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Date: 11 Dec 2018 Inspected by:

Name: .....

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	ン ン ン ン ン			
Smoke & fumes Performance Noise  Cooling System Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise	ν ν			
Performance Noise  Cooling System Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise	ν ν			
Noise  Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)  Transmission  Operation  Noise	ν ν			
Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)  Transmission  Operation  Noise	ν ν			
Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise				
Performance Radiator / Hoses (visual)  Transmission  Operation  Noise				
Radiator / Hoses (visual)  Transmission  Operation  Noise	ν ν			
Transmission Operation Noise	<b>'</b>			
Operation Noise				
Noise				
	<b>'</b>			
Clutch	<b>'</b>			
			~	
CV joints	<b>'</b>			
Wheel bearings	~			
Brakes				
Performance	<b>'</b>			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	<u>-</u> s)	
Left front	5	5	mm	
Right front	4.	.5	mm	
Left rear	1.	.5	mm	
Right rear	2.5		mm	
Spare		Yes		
Suspension				
Suspension performance	•			
Steering performance	<b>'</b>			
Shock absorbers	<b>'</b>			
Air Conditioning / Heater				
Operation	•			
Electrical / Accessories				
Head lights	•			
Tail lights	•			
Indicators	<b>'</b>			
Dashboard warning lights	•			
Wipers (front & rear)	<b>'</b>			
Window winder FL	•			
Window winder FR	<b>'</b>			
Window winder RL	V V V V V V			
Window winder RR	<b>/</b>			
Rear view mirrors	<b>'</b>			
Radio (basic test only)	<b>'</b>			
CD (basic test only)	<b>'</b>			
Number of keys	2			
Central locking	•			
Remote locking	<b>'</b>			
Sat. Nav. (basic test only)			~	
Reversing camera			<b>'</b>	

Signature: .....