

Report ID: 18,605,061 Version: 1 22 Oct 2018 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:	KTD684	Reg Expiry:	08 Aug 2019	Engine			L
WoF Expiry:	04 Aug 2019	Odometer:	91,627 Kms	Good No:	18605061	Oil level	~		
VIN:	7AT0C139X17200093	Next Service:	93,100	Service Histor		Smoke & fumes	v		
					,	Performance	~		
	port is not a warranty		6	Danta hava nat	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	S	-0	SC SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	EID S	Operation	~		
R = rust PT = paint def				$\prod$	JHIA	Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	sc PIK			AL.	ENR	Wheel bearings	~		<u> </u>
SC = stone chi	ps V	LA		JAL)	&	Brakes	V		
W = significant scuffs						Performance	~		
		Note: som		may not be disr	laved in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftyre	
						Left front			
								2	mm
						Right front		2	mm
						Left rear		4 mm	
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			<u> </u>
						Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation	~		
Good						Electrical / Accessories			T
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dusinood						Window winder FL	~		ļ
Concret	ommonts					Window winder FR	~		<u> </u>
General Comments Noise from engine bay while take off, engine mountings need attention						Window winder RL	~		<u> </u>
NOISE ITOIT	engine bay while take t	on, engine moun	tings need attention			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
Engine Timing Mechanism:						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Mathew Varghese						Date: 22 Oct 2018			
Inspected by. Wathew Vargnese Date: 22 Oct 2018									
I have read and understood this condition guide. Name:									