


Make:	Lexus	Model:	LS400	Body Style:	Sedan
Year:	1993	Registration:	UL969	Reg Expiry:	20 Apr 2019
WoF Expiry:	13 Mar 2019	Odometer:	152,322 Kms	Good No:	18605383
VIN:	JT753UF1000178859	Next Service:		Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs


Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Comments

Seats	Average
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	✗		
Smoke & fumes	✗		
Performance	✗		
Noise	✗		
Cooling System			
Coolant condition	✗		
Performance	✗		
Radiator / Hoses (visual)	✗		
Transmission			
Operation	✗		
Noise	✗		
Clutch			✗
CV joints			✗
Wheel bearings	✗		
Brakes			
Performance	✗		
Hand Brake	✗		
Tyres (lowest observed tread depth of tyres)			
Left front	6	mm	
Right front	6	mm	
Left rear	6	mm	
Right rear	6	mm	
Spare		Yes	
Suspension			
Suspension performance	✗		
Steering performance	✗		
Shock absorbers	✗		
Air Conditioning / Heater			
Operation	✗		
Electrical / Accessories			
Head lights	✗		
Tail lights	✗		
Indicators	✗		
Dashboard warning lights	✗		
Wipers (front & rear)	✗		
Window winder FL	✗		
Window winder FR	✗		
Window winder RL	✗		
Window winder RR	✗		
Rear view mirrors	✗		
Radio (basic test only)	✗		
CD (basic test only)		✗	
Number of keys	3		
Central locking	✗		
Remote locking	✗		
Sat. Nav. (basic test only)			✗
Reversing camera			✗

Inspected by: Stuart Melbourne

Date: 09 Nov 2018

I have read and understood this condition guide.

Name:

Signature: