

Report ID: 18,605,486 Version: 14 08 Apr 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	GTS183	<b>Reg Expiry:</b>	29 Oct 2018	Engine			1
WoF Expiry:	19 Apr 2020	Odometer:	146,253 Kms	Good No:	18605486	Oil level	~		
VIN:	VSKCVND40A0388706	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	S PT SC		S SC S		S	Performance	~		
Key:	Laria (	-0	330 3	500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
B = rust				210	HIV	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					D PT SC	Clutch			~
P = pin dent	HIP				74114	CV joints	~		
* = decals	sc 916			The second	FID SPT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S PT						Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments FL door key barrel cover missing						Tyres (lowest observed tread depth of tyres)			2s)
FL door key barrel cover missing						Left front	6.0 mm		mm
						Right front	6.	0	mm
						Left rear	7.	0	mm
Conditions During Body Inspection: Dry					Right rear	7.0 mm		mm	
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	/ Telege					Indicators	~		
Panels	Average-fe	ew panels missin	g			Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	•				· · · · · · · · · · · · · · · · · · ·	Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Jason Law Date: 05 Apr 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....