


<b>Make:</b>	Mitsubishi	<b>Model:</b>	Pajero	<b>Body Style:</b>	SUV
<b>Year:</b>	2004	<b>Registration:</b>	BWS414	<b>Reg Expiry:</b>	04 Apr 2019
<b>WoF Expiry:</b>	16 Jul 2019	<b>Odometer:</b>	204,017 Kms	<b>Good No:</b>	18607420
<b>VIN:</b>	JMFLYV77W4J002439	<b>Next Service:</b>	?	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Paint flaking off front bumper, left side running board & large stone chips on front of bonnet. Radio aerial has been taped up. Stone chips in windscreen.

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

Minor oil leak from gearbox. Jack handle is missing.

## Interior Comments

Seats	Average
Carpets	Good
Panels	Good
Dashboard	Good

## General Comments

Engine & transmission need a service. Hole in side of drivers seat. Scratches in tinting on both right & left rear windows & left rear door window. Cd player not working. Ash tray missing out of rear of centre console. Rips in top corners of both pockets, that are on rear of both front seats.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	4.2	mm	
Right front	4.1	mm	
Left rear	1.7	mm	
Right rear	1.9	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 29 Oct 2018

I have read and understood this condition guide.

Name: .....

Signature: .....