

Report ID: 18,607,703 Version: 1 23 Oct 2018 Created:

| Make: | KIA | Model: | Sorento | Body Style: | Wagon | | Pass | Fail | N/A |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------|------------------------|-------------------|-----------------------------------------------------------------------------------------|-----------------------------|--------------------------------|--------|----------|
| Year: | 2013 | Registration: | LQG932 | Reg Expiry: | 06 Sep 2019 | Engine | | | |
| WoF Expiry: | 07 Sep 2019 | Odometer: | 23,951 Kms | Good No: | 18607703 | Oil level | ~ | | |
| VIN: | KNAKU816ME547078. | Next Service: | 33747 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is made | for one and miles as | Dauta hava nat | heen discontined or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | | _ | | | | Performance | ~ | | |
| Key: | | -0 | LS | -161- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | The | EID S | Operation | ~ | | |
| R = rust PT = paint def | | | | \int | JHIH | Noise | ~ | | |
| C = crack | | | | + | | Clutch | | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | • |
| * = decals | s 916 | | | The | EII PR- | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | L |
| W = significant scuffs | | | | | | Performance | ~ | | |
| | | Note: som | ne defects & blemishes | may not be disr | laved in the diagram | Hand Brake | ~ | | |
| Body Insp | pection Comments | | | indy not be disp | | | | oftyre | () () |
| | | | | | Tyres (lowest observed tread depth of tyres) Left front 40 mm | | | | |
| | | | | | | Right front | 4. | | mm |
| | | | | | | Left rear | 5. | | mm |
| | | | | | | | 4. | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear 5.0 mm | | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare N/A Suspension | | | |
| <u></u> | | | | | | Suspension performance | | | |
| | | | | | | | ~ | | |
| | | | | | | Steering performance | | | |
| | | | | | | Shock absorbers | ~ | | <u> </u> |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | - | | |
| | | | | | | Electrical / Accessories | | | |
| Seats | 5 | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | / | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| General | Comments | | | | | Window winder FR | ~ | | |
| | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | Ĺ |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| Engine Ti | ming Mechanism: | Time !:= | Chain | | | Remote locking | ~ | | |
| - | - | Timing (| | Kma | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspecte | d by: Greg Morgan | | | | | Date: 23 Oct 20 | 18 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name: