

Report ID: 18,608,029 Version: 1 18 Oct 2018 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	DWD387	Reg Expiry:	12 Apr 2019	Engine	I		1
WoF Expiry:	04 Apr 2019	Odometer:	159,025 Kms	Good No:	18608029	Oil level	~		
VIN:	WVWZZZ9NZ7Y14798	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for one and miles as	Dauta hava nat	hoon diamonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:	P W	-0	P P			Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	s dla			the	EID S	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+	SC	Clutch	~		
P = pin dent	Ho				JUII —	CV joints	-		
* = decals	sc pp			AL-	ENR	Wheel bearings	~		
SC = stone chips							~		
W = significant scuffs W S P W D						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<b>6</b> .	Ļ
Windscreen chips						Tyres (lowest observed tread depth of tyres)			
						Left front	3	3	mm
						Right front	3	3	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	4	1	mm
						Spare	Spare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation	~		
Interior Comments						Electrical / Accessories			-
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		1
						CD (basic test only)	~		1
						Number of keys	2		1
Road Con	ditions During Test	Drive:	Dry		]	Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L	-	-							
Inspecte	d by: John Lindsay	Date: 18 Oct 20	18						
I have read and understood this condition guide. Name:									