

Report ID: 18,608,103


Version:

Created: 19 Oct 2018

Make:	Isuzu	Model:	D-MAX	Body Style:	Utility
Year:	2014	Registration:	HRL447	Reg Expiry:	15 Jan 2019
WoF Expiry:	05 Oct 2019	Odometer:	183,508 Kms	Good No:	18608103
VIN:	MPATFS85JFT001607	Next Service:	185,000kms	Service Histor	y: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper misaligned Left wing mirror damage

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak around turbo

Interior Comments				
Seats	Average			
Carpets	Carpets missing			
Panels	Average			
Dashboard	Average			

General Comments

Engine mounts weak

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

19 Oct 2018 Inspected by: Ca Thach Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		9	mm
Right front		9	mm
Left rear		9	mm
Right rear		9	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	V		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	V		
CD (basic test only)	V		
Number of keys	2		
Central locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Remote locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Sat. Nav. (basic test only)	+		1
Reversing camera			1
versning curnera			

Signature: