

Report ID: 18,608,671 Version: 1 22 Oct 2018 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A
Year:	2005	Registration:	CUZ124	Reg Expiry:	10 Aug 2019	Engine	•		
WoF Expiry:	02 Nov 2019	Odometer:	178,105 Kms	Good No:	18608671	Oil level	~		
VIN:	KMHEU41FR5A08022	Next Service:	188000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and ti	his can be arranged to	r an additional o	narge.	Coolant condition	~		
	Р		PT PT			Performance	~		
Key:	r (-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		1
R = rust	s sc			210	Ell Is	Operation	~		
PT = paint def	ect NP				111/1	Noise	~		
C = crack					S D	Clutch			~
P = pin dent * = decals SPT SC 000						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts PT PW SP W SPT						Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
CD player not tested						Tyres (lowest observed tread depth of tyres)			
						Left front 5.0 n			mm
						Right front	5	.0	mm
						Left rear	1	.5	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil seepage	e from front engine area	I.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments R/F Seat Worn , Elec seat R/ F N/W						Electrical / Accessories			
Seats	R/F Seat W	/orn , Elec seat R/	′ F N/W			Head lights	~		
Carrata	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	-					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
E Frankting Tr			- ·			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Buckley Date: 18 Oct 2018									
Inspected by. Chins buckley Date: 18 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: