

Report ID: 18,608,750 Version: 1 19 Oct 2018 Created:

Make:	BMW	Model:	Z4	Body Style:	Convertible		Pass	Fail	N/A
Year:	2006	Registration:	 KSG955	Reg Expiry:	01 Jul 2019	Engine			I
WoF Expiry:	04 Oct 2019	Odometer:	42,385 Miles	Good No:	18608750	Oil level	~		
VIN:	WBABU52050LL90161	Next Service:	now42	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			715	HIV	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack					S	Clutch	~		
P = pin dent	HIR				74 <u>11</u> 4	CV joints	~		
* = decals	s gle			The second	ELD'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant	S S		SP	S	S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	l depth	of tyre	es)
					Left front	5	5	mm	
						Right front	e		mm
						Left rear	e		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
								N/A	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	ning Mashaultur	_				Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Eddie Marsters Date: 19 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: