

Basic Vehicle Condition Guide

Report ID: 52,271

Version: 2

Engine

Oil level

Created: 19 Feb 2019

Pass


Fail

N/A

Make: Model: Volkswagen Beetle **Body Style:** Hatchback Year: 2001 Registration: EPM971 Reg Expiry: 31 May 2019 **Odometer:** WoF Expiry: **Good No:** 22 Nov 2019 181,413 Kms 18608797 VIN: WVWZZZ9CZ2M6027! Next Service: 188000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions	During	ı Bodv	Inspection

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

A/C not cold

Glove box latch broken

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

/		
~		
~		
~		
~		
~		
		•
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
3	.0	mm
3	.0	mm
4	.0	mm
4	.0	mm
	Yes	
~		
~		
1		
1		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1		
	т —	
~		
v v		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name:

Signature:

07 Nov 2018

Reversing camera