

Report ID: 18,608,848 Version: 1 18 Oct 2018 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	DKS17	Reg Expiry:	25 Jan 2019	Engine			
WoF Expiry:	05 Jul 2019	Odometer:	226,676 Kms	Good No:	18608848	Oil level	~		1
VIN:	JM0GY103200302472	Next Service:		Service Histor		Smoke & fumes	~		+
	511103200502172		220031			Performance	~		+
	port is not a warranty		C 1 11	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		1
						Performance	~		
Key:	PT SC	-0	SP SP			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The	EID S	Operation	~		1
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+	PT SC	Clutch	•		~
P = pin dent						CV joints	~		
* = decals	PT SC PT SC			AL-	ENPR-	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs SC W P						Performance	~		T
		Nataron	e defects & blemisher			Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftur	
Suntan lotion damage on paint. Stonechips on windscreen. Central and remote locking not working on RF door.						Tyres (lowest observed tread depth of tyres)			
LF window not shutting from RF switch. Airvent in center of dash damaged.						Left front		3	mm
						Right front Left rear		1	mm
								3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Inner edge wear both rear tyres.						Suspension			1
inner edge	wear both rear tyres.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation	~		
Average						Electrical / Accessories			T
Seats	, weitige					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		—
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Constal						Window winder FR	~		<u> </u>
General Comments					Window winder RL	~		<u> </u>	
Petrol gauge inaccurate.					Window winder RR	~		<u> </u>	
Drives ok.						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	_	
Road Con	ditions During Test	t Drive:	Dry			Central locking		~	
						Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by Pager King						Date: 19 Oct 2019			
Inspected by: Roger King Date: 18 Oct 2018									
I have read	and understood th	is condition a	juide. Name:			Signature:			